



DIGITAL MAX/MIN THERMOMETER



Operating Instructions

INSTRUMENT OPERATION - Remove the battery cover and insert the AA battery supplied. The thermometer should be positioned away from direct sunlight and draughts to ensure an accurate reading. The minimum reading indicates how low the temperature has dropped, and the maximum reading indicates how high the temperature has risen. The current temperature is displayed in the centre of the instrument. To reset the readings, press the CLEAR button. To switch the current reading between °C & °F, press the °C/°F button on the side of the unit.

GUARANTEE - This instrument carries a one-year guarantee against defects in either components or workmanship. During this period, products that prove to be defective will, at the discretion of ETI, be either repaired or replaced without charge. The product guarantee does not cover damage caused by fair wear and tear, abnormal storage conditions, incorrect use, accidental misuse, abuse, neglect, misapplication or modification. Full details of liability are available within ETI's Terms & Conditions of Sale at etiltd.com. In line with our policy of continuous development, we reserve the right to amend our product specification without prior notice.



Supplied by
Electronic Temperature Instruments Ltd
Worthing · West Sussex · BN14 8HQ
01903 202151 · sales@etiltd.com · etiltd.com

